

#### Vehicle Factors

Steven L. Prouty

#### Overview

- Condition of brakes
- Onboard brake stroke monitoring systems
- Vehicle weight
- Onboard vehicle weighing systems
- Lift axle air brake installation



#### Accident Truck






#### Condition of Brakes

- Of 8 brakes in service:
  - 1 out-of-adjustment by <sup>1</sup>/<sub>4</sub> inch
  - 2 at adjustment limit
  - 1 within <sup>1</sup>/<sub>8</sub> inch of adjustment limit
- Approximate 17% reduction in braking efficiency
- Increased collision severity




# Onboard Brake Stroke Monitoring Systems

- Previous recommendations to NHTSA
- Incorporate sensors into foundation brakes
- Driver interface
  - In adjustment
  - Within <sup>1</sup>/<sub>8</sub> inch of adjustment limit
  - At or exceeding adjustment limit





### Overweight Vehicle Route





#### Overweight Vehicle Route

- Driver required to use closest scale to pickup location
- Overweight citations issued as result of crash
- No policies, procedures, or driver oversight by company



#### Overweight Vehicle

- Gross vehicle weight: 84,950 pounds
- Approximate 9% reduction in braking efficiency

Registered weight (80,000 pounds)

Tire we


Tire weight ratings exceeded



Gross axle weight ratings exceeded



New Jersey axle group restriction (56,400 pounds)



Axle weight (pounds)

15,100

12,800

29,000

28,050

69,850



## Onboard Vehicle Weighing Systems


 Use load cells, air pressure transducers, or strain gages



- Driver interface
  - Provides axle weights, cargo weights, and/or gross vehicle weight
- $\sim$  \$2,000 \$7,500
- Original equipment or aftermarket




### Lift Axle Brake Piping Installation






#### Lift Axle Brake Piping Installation






#### Results of Improper Installation

- 2003 FMVSS 121 requirements:
  - Application (0-60 psi) within 0.45 second
  - Release (95-5 psi) within 0.55 second









#### Summary

- Braking efficiency degraded by
  - Brake defects
  - Vehicle weight
- Lack of route oversight for overweight vehicle
- Onboard brake stroke monitoring
- Onboard vehicle weighing systems
- Improper lift axle brake installation





## National Transportation Safety Board